

VEGAFLEX 80 four-wire Modbus

HW version, available since	Description
1.0.1 05/2019	Modifications compared to HW version 1.0.0: <ul style="list-style-type: none"> – Cause for the failure of individual instruments with error message F040/8000 "Failure in the electronics" due to too low signal amplitude <ul style="list-style-type: none"> ○ Adaptation of the filter damping to increase the signal amplitude

Legend:

Name	Description
HW version	Compatibility version.Function extension version.Error correction version
available since	Month/Year